

## Under Review Notification

**Raised By:** Vanessa Morel

**Product #:** T-TM1581

**Date:** 2019.10.29

**Product Name:** SAMPLING TOOL

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
T-TM1581	T-TM158 Rev	Y	Y	N	Y	Y	N	N	N	19-1073	See below

**Description of Issue:**  
 Issues stated on ADR (Safety issue, items missing)  
 T-TM1581 and items -1 and -3 must be put on **HOLD** in Plex  
 T-TM1581 Finish good stock must be put in quarantine  
 Items -1 and -3 stock must be put in quarantine  
 No new manufacturing is permitted until Engineering release new Rev  
 Can remain on website with a note to contact sales for a quote. They must **NOT** be able to put the tool into cart  
 'P' Part must be put on **HOLD** in Plex as well

<b>Distribution:</b>	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene